



| Поз | Наименование детали |
|-----|--------------------------------|
| 1 | Right support seat |
| 2 | Left support seat |
| 3 | Guide shaft |
| 4 | Fries machine guide rod gasket |
| 5 | Support seat fixing rod |
| 6 | Guide trough |
| 7 | Wing nut |
| 8 | Pushing head mounting seat |
| 9 | Pushing head |
| 10 | Push handle mounting plate |
| 11 | Pushing head handle |
| 12 | Pushing head handle rocker |
| 13 | Blade assembly mount |
| 14 | Blade assembly |
| 15 | Nut M8 |
| 16 | Pin shaft |
| 17 | Split pin |
| 18 | Fixing screw |